US ERA ARCHIVE DOCUMENT

U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT

Kalamazoo River/Enbridge Spill - Removal POLREP-SITREP



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V



Subject: SITREP # 79

Kalamazoo River/Enbridge Spill

Z5JS

Marshall, MI

Latitude: 42.2395273 Longitude: -84.9662018

To: Lt. Paul Baker, Kalamazoo County Sheriff's Office

James Rutherford, Calhoun County Public Health Department
Durk Dunham, Calhoun County Emergency Management
Prior Whitsett Michigan State Police Emergency Management

Brian Whitsett, Michigan State Police, Emergency Management.

Mark DuCharme, MDNRE

Mike McKenzie, City of Battle Creek

Susan Hedman, U.S. EPA Regional Administrator

James Sygo, MDNRE

From: Ralph Dollhopf, U.S. EPA, Federal On-Scene Coordinator

Tricia Edwards, U.S. EPA, On-Scene Coordinator Jeff Kimble, U.S. EPA, On-Scene Coordinator Stephen Wolfe, U.S. EPA, On-Scene Coordinator

Date: 12/14/2010

Reporting Period: 0700 hours 12/06/2010 to 0700 hours 12/13/2010

1 Introduction

1.1 Background

1.1.1 Site History

Background Information

Site Number: Z5JS Contract Number: D.O. Number: Action Memo Date:

Response Authority:OPAResponse Type:EmergencyResponse Lead:PRPIncident Category:Removal Action

NPL Status: Non-NPL Operable Unit:

Mobilization Date: 7/26/2010 **Start Date:** 7/26/2010

Demob Date: Completion Date:

CERCLIS ID: RCRIS ID:

ERNS No.: State Notification:

FPN#: E10527 Reimbursable Account:

1.1.2 Preliminary Site Inspection and Response Activities

See SITREP #51 for a comprehensive description of preliminary operations.

1.2 Response Status

Governance for the project is provided by the U.S. EPA Federal On-Scene Coordinator (FOSC) and the Michigan Department of Natural Resources and the Environment (MDNRE). The Operational Period covered in this report is: 12/06/2010 07:00 to 12/13/2010 07:00.

1.3 Operations Section

This operational phase of the response consists of: 1) Long Term Operations and Maintenance (O&M); 2) Drinking/Groundwater Monitoring; 3) Decontamination; and 4) Other Operations.

1.3.1 Long Term Operations and Maintenance (O&M)

Teams inspected O&M locations. In general, team activities included an inspection of sorbent material (boom, pads and/or pom-pom) to ensure proper placement and effectiveness. Teams performed inspection for readily visible contamination. A summary of significant actions for this period is presented in Table 1.

Table 1 – O&M Actions

	Number of	
Activity	Locations	Location (MP)
Sheen observation	20	2.25 L2; 2.50 L1; 2.75 I1; 2.75 L1; 3.75 LIC;
		3.75 RIC; 5.55 N; 7.00 R1; 8.50 L1; 8.50 L2;
		9.00 I1; 10.50 L2; 10.75 L2; 11.00 R1; 11.25
		R1; 11.50 R1; 12.00 R1; 15.00 L1; 17.00
		(RockTenn); 21.50
Flushing	2	5.55N; 21.5
New Work Plans Prepared or	15	2.50 L1; 2.75 I1; 3.25 R1; 3.75 LIC; 3.75 RIC;
Pending		7.00 R1; 8.50 L1; 8.50 L2; 9.00I1; 10.5 L2;
		11.25 R1; 11.25 R2; 11.50 R1; 12.00 R1;
		17.00 (RockTenn)1
Boom Removal	13	C6; D1; D3; E4; E5; 5.55N; 21.50
Hydro Vacuuming	1	3.25 IA
Vegetation Removal	1	13.00 R1
Additional Excavation	1	13.00 R1
Submerged Oil Recovery	4	5.55 N; 11.75 R1; 21.50; 10.75 L2
Off-Site Cleaning	1	17.00 (RockTenn)

The O&M process is documented in Table 2.

Table 2 – O&M Maintenance and Monitoring Areas

	Area Status
O&M Process	12/12
Active	2
Monitoring	39
Cleared	8
Signed Off	50

1.3.2 **Drinking and Groundwater Studies**

Drinking water well sampling of 17 wells was performed during this period by Enbridge under MDNRE oversight.

1.3.3 **Decontamination**

Equipment and boom that were decontaminated during this operational period are summarized in Table 3.

Table 3 - Equipment Decontamination

Location/Media	Totals	12/12	12/11	12/10	12/9	12/8	12/7	12/6
Frac Tanks	1	0	0	0	1	0	0	0
Vac Trucks-Tankers	1	0	0	1	0	0	0	0
Roll-Off Boxes	0	0	0	0	0	0	0	0
Yellow Iron - Light	0	0	0	0	0	0	0	0
Yellow Iron - Heavy	0	0	0	0	0	0	0	0
Marine Vessels	23	9	6	2	2	0	4	0
Vehicles	2	0	2	0	0	0	0	0
Daily Total	27	9	8	3	3	0	4	0
Boom (feet)	300	0	0	0	0	0	0	300

1.3.4 Additional Operations

Air Operations

- During this operational period, there were 5 over-flights for situational awareness.
- Air Ops observed and documented O&M progress in all operational areas.
- Air Ops continued to investigate/report areas of interest, oil mobilization, O&M, and decontamination.

Environmental Compliance and Oversight

- Continued waste management characterization, documentation, and coordination.
- Coordination with the MDNRE continues, particularly with regards to MDNRE concurrence of work contemplated by Enbridge in ecologically sensitive areas during winter operations.

Monitoring Branch

- Under MDNRE direction, performed sediment and surface water sampling at Lake Morrow
 in accordance with the existing U.S. EPA-approved Sampling and Analysis Plan (SAP),
 (adopted by MDNRE) and a reduced sampling frequency as approved by the MDNRE.
- Samples reported by Enbridge are provided in Table 4.

Table 4 – Samples Collected By Enbridge

	Number Collected											
Sample Type	Totals	Totals 12/12 12/11 12/10 12/9 12/8 12/7 12/6										
Surface Water	13	0	0	0	4	3	6	0				
Private Well	17	0	0	0	2	4	11	0				
Groundwater	9	0	0	0	1	4	4	0				
Sediment	8	0	0	0	0	8	0	0				
Soil Samples	31	0	0	0	8	5	18	0				

Landowner Environmental Issues

Landowner environmental issues for the referenced period are represented in Table 5.

Table 5 – Landowner Environmental Issues

Issues this Period	Issues Undergoing Evaluation	Issues Considered Addressed
1	12	24

1.3.5 **Progress Metrics**

All progress metrics in Section 1.3.5 are as reported by Enbridge unless otherwise indicated.

Table 6 - Boom Report

Metric	12/12	12/11	12/10	12/9	12/8	12/7	12/6
Number of Locations	29	31	42	42	42	42	42
Boom Deployed (feet)	12,680	13,980	18,280	20,460	26,468	27,838	38,608

NR = Per Enbridge, data not recorded

Table 7 - Soil and Debris Shipped Off Site as of 12/12

Waste Stream*	Cumulative [†]
Haz Soil (yd ³) ^a	19,644
Non Haz Soil (yd ³) ^{b, d}	64,347
Non Haz Soil (yd ³) ^{b, e}	5,562
Haz Debris (yd ³) ^c	12,075
Non Haz Household Debris (ton)	187
Non Haz Impacted Debris (ton) ^c	1,474

- * Information for water (other than daily quantity shipped) is reported in other tables below. Quantity awaiting disposal is estimated
- † Due to the auditing of waste manifests, cumulative quantities may not reconcile with previous reports.
- a. Haz soil (benzene impacted) is being transported to Envirosafe (Oregon, OH).
- b. Non Haz soil is being sent to Westside Recycling (Three Rivers, MI) and EQ/Republic (Marshall, MI).
- c. Roll-off boxes containing waste sorbents, boom, pads, plastic, PPE, and oiled vegetation and biomass are being sent to EQ facility (Michigan Disposal) in Wayne, MI and Republic (Marshall, MI).
- d. Excludes dredge spoils from Ceresco.
- e. Includes only dredge spoils from Ceresco.

Oil/Water Recovery Tracking:

Note: Some of the values in the tables below have been audited and reconciled by Enbridge and may not correlate with previously reported values.

Table 8 – Oil/Water Collected by Location (as of 12/12)

	Cumulative
Location	(gallons)
Division A	5,338,315
Division B	4,843,782
Division C	1,521,964
Division D	114,906
Division E	47,438
Decontamination	929,185
Other Locations*	955,331
Total	13,750,922

^{*} Includes fluids stored in Fractionation Tanks which was generated from Decontamination Operations, Wildlife Center Operations, Sediment Trap Cleaning, Hydro-Vacuuming activities.

Table 9 – Oil/Water Separation 12/12 (Enbridge Facility in Griffith, IN) (Gallons)

Item	Cumulative (gallons)
Oil	766,288
Other Material	1,405,525
Total	2,171,813

Table 10 - Oil/Water Remaining On-Site (Gallons)

	Cumulative
Item	(gallons)
Oil/Water Collected	13,750,922
Oil/Water Shipped Off-Site	13,730,587
Oil/Water Remaining On-Site	20,335

Table 11 - Liquid Shipped Off-site as of 12/12

		Destination	Cumulative
Stream	Destination Company	Location	Volume (gallons) †
Hazardous Water	Dynecol	Detroit, MI	3,458,329
Oil/Water	Enbridge Facility	Griffith, IN	2,171,813
Treated Non-Haz Water	Treated Non-Haz Water Liquid Industrial Waste		370,200
Treated Non-Haz Water	reated Non-Haz Water Plummer		4,976,140
Hazardous Water Safety Kleen ^a			825
Treated Non-Haz Water*	Dynecol	Detroit, MI	150,700
Treated Non-Haz Water*	Battle Creek POTW	Battle Creek, MI	1,968,700
Non-Haz Water		Battle Creek, MI	166,220
Sludge			467,660
	•	Total	13,730,587

- * Treated Non Haz Water no longer sent to this location.
- † Cumulative quantities may not reconcile with previous reports (due to auditing).
- a. New Age lab water and methanol mix generated by mobile laboratory.

1.4 Planning Section

Environmental Unit

Nothing to report.

Data Management Unit

- Continued importing preliminary and validated analytical results into Scribe, exporting daily briefings; and processing and printing maps as requested.
- Database management is being done in Houston.

Documentation Unit

Continued organization and archiving of electronic files.

1.5 Safety Reports

Cold weather (below freezing) has been continuously present and ice formation has been observed in slower moving portions of the river. Safety stand-downs were conducted December 7th for all staff and December 8th to address drilling and intrusive activities.

No safety concerns were reported during this operational period. Safety inspections occurred throughout the operational area.

1.6 Liaison Officer

Nothing to report.

1.7 Public Information Officers

Received public inquires as outlined in 12.

Table 12 - Public Inquiries Received by EPA and Enbridge

Tubic 12 Tub	Table 12 - 1 ubite inquiries Received by ETA and Embridge							
	Inquiries Received							
Location/Media	Total	12/12	12/11	12/10	12/9	12/8	12/7	12/6
Battle Creek Community Center	37	0	1	8	9	9	6	4
Marshall Community Center	19	0	0	7	3	4	3	2
Oil Spill Public Information Hotline	31	0	2	5	2	8	7	7
Enbridge Response Website								
(www.response.enbridgeUS.com)	1	0	0	0	1	0	0	0
Total Public Inquiries	88	0	3	20	15	21	16	13

1.8 Finance Section

The current NPFC issued ceiling is \$27.6 Million. Approximately 85.2% of the ceiling has been spent through December 11, 2010, with the latest average burn rate of \$30,995 per day. These cost summaries reflect only EPA-funded expenditures for the incident. A summary of these expenses is presented in 13.

Table 13 - Financial Summary

Table 13 - Financial Summary										
			Expended (Cumulative) as of							
Item	n		12/4							
ERRS Contractors										
EQM (EPA 50802)	T)57	\$	1,250,065						
	T()60	\$	204,905						
LATA (EPA 50804)			\$	1,451,396						
ER LLC (EPS 50905)			\$	723,669						
Total ERRS Contractors				3,630,035						
Lockheed Martin (EPW 09031) – TAGA Support			\$	150,000						
T&T Bisso (EPA:HS 800008 USCG:HS CG8410A 800008)				1,255,000						
START Contractor – WESTON (E	PS 50604)	T030-Response	\$	8,519,380						
		T032-Sampling	\$	180,214						
T037-Doc Support				355,276						
Resp	\$	14,089,905								
EPA Funded Costs: Total EPA Costs				4,752,630						
Pollution Removal Funding Agreements – Total Other Agencies			\$	1,426,909						
		Sub-Totals	\$	20,269,444						
Indirect Cost (16.00%)			\$	3,243,111						
Total Est. Oil Spill Cost			\$	23,512,556						
Oil Spill Ceiling Authorized by US	CG		\$	27,600,000						
Oil Spill Ceiling Available Balance			\$	4,087,444						

1.9 Response Actions to Date

Response Actions to date may be found in SITREPs #1 through #78.

2 Participating Entities

2.1 Multi-Agency Coordination Group

U.S. Environmental Protection Agency
Michigan Department of Natural Resources and the Environment
Michigan State Police Emergency Management Division
City of Battle Creek City of Marshall Calhoun County Public Health Department Calhoun County Emergency Management Kalamazoo County Sheriff Enbridge (Responsible Party)

2.2 Cooperating and Assisting Agencies and Congressional Presence

For a list of cooperating and assisting agencies and the congressional presence, see SITREP #51.

3 Personnel On-Site

Staffing numbers for the various entities and agencies active in the response are presented in Table 14.

Table 14 - Personnel On-Site

	Personnel Count								
Agency/Entity	12/12	12/11	12/10	12/9	12/8	12/7	12/6		
U.S. EPA	6	6	6	6	7	7	9		
START	21	21	22	22	23	23	24		
Calhoun County Public Health	0	0	0	1	0	0	0		
Calhoun Count (CC) EM	0	0	0	1	0	0	0		
City of Battle Creek	0	0	0	1	0	0	0		
City of Marshall	0	0	0	1	0	0	0		
Kalamazoo Sheriff	0	0	0	1	0	0	0		
MDNRE	4	0	3	1	3	3	3		
Michigan State Police EMD	0	0	0	1	0	0	0		
NOAA – National Weather	0	0	0	0	0	0	0		
USFWS	0	0	0	0	0	0	0		
Enbridge – Operations*	4	9	11	11	11	11	12		
Enbridge – Operations Contractor*	51	109	132	141	155	150	152		
Enbridge – Field*	1	1	1	1	1	1	1		
Enbridge – Field Contractors*	81	83	165	173	157	192	206		
Total	168	229	340	361	357	387	407		

Enbridge personnel counts are from 07:00 on the day shown.

4 Source of Additional Information

For additional information, refer to http://www.epa.gov/enbridgespill. For sampling analysis data, see http://response.enbridge.com/response/main.aspx?id=13168.